

JOYALL TRUCK TIRE ROAD TESTING PROGRAM

Customer: IMPEL Transport Ltd
 Installation Mileage: 0Km
 Inspection Date: 24/09/2018
 Inspection Mileage: 53,549Km
 Vehicle Reg. No.: Trailer

Tire Position	Tread River			
	Outside	Middle Outside	Middle Inside	River Inside
RO 115psi	11.85	13.33	13.5	11.96
	11.87	13.26	13.67	11.99
	11.13	13.39	13.33	12.24
	11.62	13.33	13.50	12.06
		13.41		
	12.63			

Tire Position	Tread River			
	Outside	Middle Outside	Middle Inside	River Inside
RI 115 psi	11.75	13.33	13.55	12.02
	12.28	13.73	13.25	11.96
	11.77	13.3	13.73	12.31
	11.93	13.45	13.51	12.10
		13.48		
	12.75			

Tire Position	Tread River			
	Outside	Middle Outside	Middle Inside	River Inside
LO 115psi	11.42	13.78	13.33	11.96
	12.32	14.23	13.49	12.28
	11.60	13.22	13.46	12.18
	11.78	13.74	13.43	12.14
		13.59		
	12.77			

Tire Position	Tread River			
	Outside	Middle Outside	Middle Inside	River Inside
LI 115 psi	12.44	14.62	14.25	11.2
	12.35	13.93	13.72	12.07
	11.96	13.71	13.38	12.18
	12.25	14.09	13.78	11.82
		13.94		
	12.98			



A876

S.N.	Tire Pattern	Origin Tread	Installed		Track Date	Mileage Km	Trip Distance	Air Pressure	Tread Read	Tread Wear	Tire Mileage	Project Tire Mileage		Total Project
		mm	Date	Mileage Km								Steer (3.18mm)	Trailer (1.59mm)	
RO	JOYALL A876 295/70R22.5	14.6	01/04/2018	0	24/09/2018	53549	53549	115	12.63	1.97	27136.32		353,043.49	353043.49
RI		14.6	01/04/2018	0	24/09/2018	53549	53549	115	12.75	1.85	28919.35		376,240.77	376240.77
LO		14.6	01/04/2018	0	24/09/2018	53549	53549	115	12.77	1.83	29301.78		381,216.14	381216.14
LI		14.6	01/04/2018	0	24/09/2018	53549	53549	115	12.98	1.62	33140.18		431,153.68	431153.68

